

Heat Treatment of Metals

MSE-S305

Ankur Katiyar

**Assistant Professor, MSME Department
UIET, CSJM University**

Critical temperatures and Phase boundaries in Fe-Fe₃C Phase Diagram

➤ *Critical temperature* shows the temperature at which phase changes occur in steel either on *heating* or *cooling*, indicating by the arrest of temperature change at that point of heating or cooling.

➤ Generally, *upper* and *lower* critical temperatures are symbolised by Ac_3 and Ac_1 , respectively, to denote critical temperatures on heating.

(The “c” is from the French word *chauffage*, stands for *heating*)

Critical temperatures and Phase boundaries in Fe-Fe₃C Phase Diagram


➤ Similarly, Ar_3 and Ar_1 , are used to denote critical temperatures on cooling.

(The “*r*” is from the French word *refroidissement*, stands for *cooling*).

➤ A_1 : The upper limit of the *ferrite/cementite* phase field. Below this temperature, *Austenite* does not exist.

➤ Horizontal line going through the *eutectoid point*.

Critical temperatures and Phase boundaries in Fe-Fe₃C Phase Diagram




Critical temperatures and Phase boundaries in Fe-Fe₃C Phase Diagram

- A_2 : The temperature where iron loses its magnetism (so-called *Curie temperature*).
- *Curie temperature (768°C): The temperature at which paramagnetic β -iron transform to ferromagnetic α -iron.*
- *β -iron: β -iron is a non-magnetic version of α -iron, is identical to α -iron in crystal structure, and exist from 768°C to 912°C.*

Critical temperatures and Phase boundaries in Fe-Fe₃C Phase Diagram

➤ **A₃**: The boundary between the *austenite* (γ -ferrite) and the *austenite/ferrite* phase field.



Critical temperatures and Phase boundaries in Fe-Fe₃C Phase Diagram

➤ A_{CM} : The boundary between the *austenite* (γ -ferrite) and the *austenite/cementite* field.

