


TTT Diagram



$v > 1000^\circ\text{C/s}$ for transforming austenite-to-martensite